

CORRIGENDUM NO 1

The roof sheet mentioned in the BOQ(Item no:-11) is TATA Trafford sheet with 0.45 mm thick